

| | CE Road Segment | Board-Endorsed Network | Rationale |
|----|---|---|--|
| 1 | Sandia Creek Drive (SC 21) Segment: Complete Segment Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes) | Minor Downgrade 2.3C Minor Collector (2 lanes) | Minimize Costs – Consistent with projected traffic volumes Minimize Environmental Impacts – Road traverses substantial terrain and sensitive environmental areas |
| 2 | DeLuz Road (SC 10) Segment: W. Mission Road to Sandia Creek Drive Existing Condition: 2 lanes Current Classification: Rural Collector (2 lanes) | Minor Upgrade 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes) | Road Capacity – Consistent with projected traffic volumes and surrounding land uses Note: Will operate at LOS E (14.7K ADTs) for approximately 3 block segment |
| 3A | E. Mission Road (SF 1305) Segment: N. Mission Road to Brandon Road Existing Condition: 2 lanes (+ continuous turn lane) Current Classification: Major Road (4 lanes) | Downgrade Classification 2.2B Light Collector with Continuous Turn Lane (2+ lanes) | Support Land Use Goals – This is an existing road with developed commercial uses, located in the Fallbrook village area Community Consensus – Road widening would adversely impact community character in a highly visible area and is opposed by the planning group Road Capacity – Parallel routes (E. Alvarado Street and local roads) provide additional road capacity Note: Will operate at LOS E (15.1K ADTs) for approximately 2 block segment |
| 3B | E. Mission Road (SF 1305) Segment: Brandon Road to Old Highway 395/I- 15 Existing Condition: 2 lanes with intermittent turn lanes Current Classification: Major Road (4+ lanes) | Minor Downgrade 4.2B Boulevard with Intermittent Turn Lanes (4+ lanes) | Road Capacity – Consistent with projected traffic volumes. Boulevards are located in Semi-Rural areas, adjustments to the visual distance requirements will be needed to the road design to ensure public safety. |

Matrix: Fallbrook -1 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|----|--|---|---|
| 4 | S. Mission Road (SF 1305) Segment: W. Mission Road to SR-76 Existing Condition: 4 lanes (with continuous turn lane) Current Classification: Major Road (4+ lanes) | Minor Downgrade 4.2B Boulevard with Intermittent Turn Lanes (4+ lanes) | Board Direction – Boulevards are located in Semi-Rural areas, adjustments will be needed to the road design to ensure public safety. The 40 mph design speed is a minimum, which should provide the flexibility needed to address both the community request (and the Board motion) and public safety concerns. |
| 5 | Main Avenue Segment: Entire segment Existing Condition: 2 lanes with intermittent turn lanes Current Classification: Light Collector (2 lanes) | Remove from CE Network Retain as Local Public Road | Support Land Use Goals – Road is not required for community circulation (S. Mission Road runs parallel) and CE requirements would be inconsistent with Fallbrook Village Revitalization Plan efforts Community Consensus – Planning Group preference |
| 6 | Alvarado Road (SC 10) Segment: Mission St to Stage Coach Lane Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes) | Minor Upgrade 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions Note: Will operate at LOS E (15.0K ADTs) for approximately 2 block segment |
| 7A | Fallbrook Street (SF 1416) Segment: S. Mission St to Stage Coach Lane Existing Condition: 2 lanes (with continuous turn lane) Current Classification: Light Collector (2 lanes) | Minor Upgrade 2.2B Light Collector with Continuous Turn Lane (2+ lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions Note: Will operate at LOS E (14.7K ADTs) for approximately 2 block segment |

Matrix: Fallbrook -2

November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|-----|---|---|--|
| 7B | E. Fallbrook Street extension (SF 1416) Segment: Stage Coach Lane to Reche Road Existing Condition: Not complete Current Classification: Rural Collector (2 lanes) | Equivalent Classification 2.2E Light Collector (2 lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions |
| 8 | Ammunition Road (SC 20) Segment: entire road Existing Condition: 4 lanes Current Classification: Collector Road (4 lanes) | Minor Downgrade 4.2B Boulevard with Intermittent Turn Lanes (4+ lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions |
| 9 | Palomino Road Segment: Old Stage Road to Stage Coach Lane Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes) | Minor Upgrade 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions Maximize Traffic Movement – Will improve connectivity within the village area and provide a link to southern commercial node |
| 10 | Pepper Tree Lane (SC 90) Segment: S. Mission Road to Stage Coach Lane Existing Condition: 2 lanes (not complete) Current Classification: Light Collector (2 lanes) | | Road Capacity – Consistent with projected traffic volumes and existing conditions Maximize Traffic Movement – Will improve connectivity within the village area and provide a link to southern commercial node Note: Will operate at LOS E (13.4K ADT) for approximately 1 block segment |
| 11A | Stage Coach Lane (SA 40) Segment: S. Mission Road to Reche Road Existing Condition: 2 lanes (+ intermittent turn lane) Current Classification: Rural Collector (2 lanes) | Minor Upgrade 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions |

Matrix: Fallbrook -3 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|-----|--|--|---|
| 11B | Stage Coach Lane (SA 40) | Minor Upgrade | Road Capacity – Consistent with projected |
| | Segment: Reche Road to E. Mission Road Existing Condition: 2 lanes Current Classification: Rural Collector (2 lanes) | 2.2B Light Collector with Continuous Turn Lane (2+ lanes) | traffic volumes |
| 12A | Gumtree Lane (SC 30) | Equivalent Classification | • Road Capacity – Consistent with projected |
| | Segment: | 2.2E Light Collector (2 lanes) | traffic volumes and existing conditions |
| | Existing Condition: 2 lanes | | |
| | Current Classification: Rural Collector | | |
| | (2 lanes) | | |
| 12B | Gumtree Lane (SC 30) | Remove from CE Network | Minimize Costs – Road segment does not provide a connection to Mission Road east |
| | Segment: Hamilton Lane to SC30 | Local Public Road (2 lanes) | of Hamilton Lane. Deletion from |
| | Existing Condition: 2 lanes | and not | Circulation Element reflects existing |
| | <u>Current Classification</u> : Rural Collector (2 lanes) | CPG Preference: | condition. |
| | (2 ranes) | Minor Downgrade | |
| | | 2.2F Community Collector with Reduced Shoulder (2 lanes) | |
| 13A | Reche Road (SF 1416) | Minor Upgrade | Road Capacity – Consistent with projected |
| | Segment: Stage Coach Lane to Green Canyon | 2.2B Light Collector with | traffic volumes and existing conditions |
| | Road | Continuous turn Lane (2+ lanes) | |
| | Existing Condition: 2 lane (with turn lanes) | | |
| | <u>Current Classification</u> : Local Public Road | | |

Matrix: Fallbrook -4

November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|-----|--|--|---|
| 13B | Reche Road (SF 1416) Segment: Green Canyon Road to Old Highway 395 Existing Condition: 2 lanes Current Classification: Rural Collector (2 lanes) | Minor Upgrade 2.2C Light Collector with Intermittent Turn Lane (2+ lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions. Road improvements are needed to handle projected traffic volumes |
| 14 | Yucca Road | Minor Upgrade | • Road Capacity – Consistent with projected |
| | Segment: Reche Road to E. Mission Road Existing Condition: 2 lanes (not complete) Current Classification: not on CE | 2.2F Light Collector with Reduced Shoulder (2 lanes) | traffic volumes and existing conditions. New CE link provides important north- south connection in a needed area |
| 15A | Old Highway 395 (SA 15) Segment: Old Highway 395/I-15 Intersection to Fallbrook CPA boundary Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) | Downgrade classification 2.1A Community Collector with Raised Median (2+ lanes) 4-lane equivalent right-of-way should be retained in case of future need | Minimize Costs – Excess traffic volumes linked to regional 2030 traffic from Riverside County. Improvement to 4-lane road would magnify attraction as road parallels I-15. Community Consensus – Consistent with planning group preference Note: Will operate at LOS E (17.2K ADTs) |
| 15B | Old Highway 395 (SA 15) | Downgrade classification | Minimize Costs – Excess traffic volumes |
| | Segment: Old Highway 395/I-15 Intersection to Pala Mesa Drive Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) | 2.1A Community Collector with Raised Median (2+ lanes) 4-lane equivalent right-of-way should be retained in case of future need | linked to regional 2030 traffic from Riverside County. Improvement to 4-lane road would magnify attraction as road parallels I-15. • Community Consensus – Consistent with planning group preference Note: Will operate at LOS E and F (17.5 to 21.1K ADTs) |

Matrix: Fallbrook -5 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|-----|---|---|---|
| 15C | Old Highway 395 (SA 15) Segment: Pala Mesa Drive to SR-76 Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) | Equivalent Classification 4.1B Major Road with Intermittent Turn Lanes (4+ lanes) CPG Preference: Minor Downgrade 4.2B Boulevard with Intermittent Turn Lanes (4+ lanes) | Road Capacity – Consistent with projected traffic volumes |
| 15D | Old Highway 395 (SA 15) Segment: SR-76 to Bonsall CPA boundary Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) | Downgrade Classification 2.1D Community Collector with improvement options (2 lanes) 4-lane equivalent right-of-way should be retained in case of future need | Minimize Costs – Excess traffic volumes linked to regional 2030 traffic. Community Consensus – Consistent with planning group preference Note: Will operate at LOS E (14.7 to 15.6K ADTs) |
| 16 | Olive Hill Road (SC 100.5) Segment: S. Mission Road to Bonsall CPA Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes) | Minor Downgrade 2.2F Light Collector with Reduced Shoulder (2 lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions |
| 17 | Green Canyon Road (SA 60.2-SC 71) Segment: Reche Road to S. Mission Road Existing Condition: 2 lanes Current Classification: Rural Collector (2 lanes) | Equivalent classification 2.2E Light Collector (2 lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions |

Matrix: Fallbrook -6 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|----|--|---|---|
| 18 | Gird Road (SA 80) Segment: Reche Road to SR-76 Existing Condition: 2 lanes Current Classification: Rural Collector (2 lanes) | Equivalent classification 2.2E Light Collector (2 lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions |
| 19 | Winter Haven Road/Palo Vista Segment: Winter Haven Road to Via Monserate Existing Condition: 2 lanes (not complete) Current Classification: Rural Collector (2 lanes) | Remove from CE Network Local Public Road (2 lanes) | Community Consensus – Planning Group preference. Projected traffic volumes consistent with a non-CE road |
| 20 | Alta Vista Road (SC 130/140) Segment: Winter Haven Road to Via Monserate Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes) | Remove from CE Network Local Public Road (2 lanes) | Community Consensus – planning group preference. Projected traffic volumes consistent with a non-CE road |
| 21 | Via Encinos/Knottwood Way Segment: S. Mission Road. to Gird Road. Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes) | Minor Downgrade 2.2F Light Collector with Reduced Shoulder (2 lanes) | Road Capacity – Provides an important east-west connection for the area Community Consensus – Planning Group preference. Consistent with existing conditions and community character (reduced shoulders) |
| 22 | Via Monserate (SC 120) Segment: S. Mission Road. to SR-76 Existing Condition: 2 lanes Current Classification: Light Collector (2 lanes) | Minor Downgrade 2.3C Minor Collector (2 lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions |

Matrix: Fallbrook -7 November 7, 2006

| l | CE Road Segment | Board-Endorsed Network | Rationale |
|-----|--|--|---|
| 23 | Pala Mesa Drive Segment: S. Mission Road. to SR-76 Existing Condition: 2 lanes (not complete) Current Classification: Light Collector (2 lanes) | Minor Downgrade 2.2F Light Collector with Reduced Shoulder (2 lanes) | Road Capacity – Consistent with projected traffic volumes and existing conditions. Road did not provide a desirable alternative to other east-west connections |
| 24A | SR-76 (Pala Road) Segment: Bonsall CPA to Old Highway 395 Existing Condition: 2 lanes Current Classification: Prime Arterial (6 lanes) | Downgrade Classification 4.1A Major Road with Raised Median (4+ lanes) CPG Preference: No Action | Minimize Costs – Consistent with SANDAG RTP and Caltrans planned improvements Minimize Environmental Impacts - Constrained right-of-way due to environmental constraints (San Luis Rey river) that do not accommodate a six-lane road Note: Will operate at LOS E (51.1 to 52.4K ADT) between Bonsall CPA and Gird Road |
| 24B | SR-76 (Pala Road) Segment: Old Highway 395 to Couser Canyon Road Existing Condition: 2 lanes Current Classification: Major Road (4+ lanes) | Equivalent Classification 4.1A Major Road with Raised Median (4+ lanes) CPG Preference: No Action | Road Capacity – Required by projected traffic volumes and consistent with existing classification |

Matrix: Fallbrook -8 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|-----|---|---|--|
| 24C | SR-76 (Pala Road) Segment: Couser Canyon Road to Fallbrook/Pala-Pauma CPA boundary Existing Condition: 2 lanes Current Classification: Major Road (4+ lanes) | Downgrade Classification 2.1D Community Collector with Improvement Options (2+ lanes) Passing lanes are the preferred improvement option. 4-lane equivalent right-of-way should be retained in case of future need CPG Preference: No Action | Road Capacity – Consistent with projected traffic volumes and existing conditions |
| 25 | Meadowood/Passarelle Road Segment: SR-76 to Canonita Drive Existing Condition: Not complete Current Classification: Light Collector (2 lanes) | Upgrade Classification 4.2A Boulevard with Raised Median (4+ lanes) | Road Capacity – Consistent with projected traffic volumes and proposed project Support Land Use Goals – Proposed road would traverse a new community with Village densities and characteristics – Boulevard's slower design speed is consistent with the desired character of the new community |
| 26 | Pankey Road (SC 260.2) Segment: SR-76 to Pala Mesa Drive Existing Condition: not complete Current Classification: Light Collector (2 lanes) | Minor Upgrade 2.1A Community Collector with Raised Median (2+ lanes) | Road Capacity – Consistent with projected traffic volumes and proposed project Note: Will operate at LOS E (14.9K ADTs) for short segment. Road segment is subject to further refinement during project processing (following project-level analysis) |

Matrix: Fallbrook -9 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|----|---|------------------------------------|---|
| 27 | Dulin Road (SC 260.2) | Equivalent Classification | • Road Capacity – Consistent with projected |
| | Segment: SR-76 to Old Highway 395 | 2.1E Community Collector (2 lanes) | traffic volumes and Lake Rancho Viejo project |
| | Existing Condition: 2 lanes | Delete Dulin Road from Circulation | project |
| | <u>Current Classification</u> : Light Collector | Element west of Old Highway 395 | |
| | (2 lanes) | | |
| 28 | Rice Canyon Road | Minor Downgrade | • Road Capacity – Consistent with projected |
| | Segment: Fallbrook/Rainbow CPA boundary | 2.2F Light Collector with Reduced | traffic volumes and existing conditions |
| | to SR-76 | Shoulder (2 lanes) | |
| | Existing Condition: not complete | | |
| | Current Classification : Rural Light Collector | | |
| | (2 lanes) | | |
| 29 | Couser Canyon Road | Minor Downgrade | • Road Capacity – Consistent with projected |
| | Segment: SR-76 to Fallbrook/Valley Center | 2.2F Light Collector with reduced | traffic volumes and existing conditions |
| | CPA boundary | shoulder (2 lanes) | |
| | Existing Condition: not complete | | |
| | Current Classification : Rural Light Collector | | |
| | (2 lanes) | | |

Matrix: Fallbrook -10 November 7, 2006